

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,820,543 B2  
DATED : November 23, 2004  
INVENTOR(S) : Hironobu Takasawa et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5.

Line 52, change "includes a damper and a damper shaft." to -- includes a clamper and a clamper shaft. --

Column 6.

Line 18, change "kozo, mitsumata," to -- *kozo, mitsumata*, --.

Line 33, change "damper rotatable about the damper shaft" to -- clamper rotatable around the clamper shaft --.

Column 7.

Line 33, change "damper" to -- clamper --.

Column 9.

Lines 31, 50 and 53, change "damper" to -- clamper --.

Column 10.

Lines 16 and 17, change "damper" to -- clamper --.


Column 12.

Lines 10, 32, 35, 37 and 45, change "damper" to -- clamper --.

Lines 19, 20 and 49, change "dampers" to -- clamps --.

Signed and Sealed this

Fifth Day of July, 2005



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*